

Glove Box

Principle

Air or moisture sensitive materials and powders can be handled in an atmosphere of purified argon.

Manufacturer	MBraun
Model	Labmaster
Inert gas	Argon
Residual concentration H₂O	≤ 0.1 ppm
Residual concentration O₂	≤ 0.1 ppm
