

# Apparent Density / Tap Density

## Principle

Determination of apparent and tap density by measurement of volume and mass of powder.

---

<b>Manufacturer</b>	Self-construction / Engelsmann AG
<b>Initial Mass</b>	Depends on material: 10 - 100 g

---