Hall-, Gustavsson-Flowmeter

Principle

Determination of flow rate of powder by means of a calibrated funnel.

Manufacturer	Self-construction
Initial Powder Mass	50 g
Measurement Range	Only free flowing powders
Result	Flow rate in seconds (without dezimals)