

Foam Binding

Principle

Manufacturing of open porous high temperature stable foams:
Coating of foams with a binder by a spraying process. Afterwards a powdercoating and sinter process is following.

Foam Size	up to 300 mm x 400 mm
Spray Volume	max. 450 g/min
